


Electric Strike  
Max 1.2 Amps



N/O  
Maintaine  
Dry Contact  
(Activation)

N/O  
To Press Fan  
(Output)